

## HOBO<sup>®</sup> CABLE-RWLMOD

Water Level Sensor Cable for RXMOD-W1

The water level sensor cable provides the connection between the HOBO RX3000 Remote Monitoring Station and the water level sensor. A HOBO RX3000 station, a water level sensor module (RXMOD-W1), and a water level sensor (MX2001-0x-S or MX2001-0x-Ti-S) are required for use with this cable.

Cables can be ordered in lengths from 1 meter to 400 meters for deployment in a wide range of applications. The 1-, 2-, 5-, 10-, 15-, 30-, and 60-meter cable lengths are standard and typically in stock. Custom cable lengths require a lead time of one to two weeks.



PLEASE NOTE: Custom cables are ineligible for return.

## Supported Measurements:

Water Level

## Key Advantages:

- Interchangeable Kevlar-reinforced cable can be used to suspend sensor
- Provides sensor communication and power
- Two O-rings in the water level sensor connector ensure a long-term waterproof seal
- Cables are easy to attach or change

## **Contact Us**

Sales (8am to 5pm ET, Monday through Friday)

- Email sales@onsetcomp.com
- Call 1-508-759-9500
- In U.S. toll free 1-800-564-4377
- Fax 1-508-759-9100

Technical Support (8am to 6pm ET, Monday through Friday)

- Contact Product Support www.onsetcomp.com/support/contact
- Call 1-508-759-9500
- In U.S. toll free 1-877-564-4377

Onset Computer Corporation 470 MacArthur Boulevard Bourne, MA 02532